

A group of seven people are gathered on a gravelly riverbank. One person is kneeling and working on a yellow kayak, which is equipped with various electronic devices and sensors. The others are standing around, observing the process. In the background, a calm river flows, and a forested hill with a small white building is visible under a clear blue sky. The scene suggests a field deployment or testing of environmental monitoring equipment.

envco

Flood, Camera, Action



Rangitopuni River, January 2023



AvoMap

0.00 km

Metairie

Mid-City

Lower Ninth
Ward


Hilton Riverside

New Orleans

Algiers

Gretna

mapbox






Monitoring Site Broken. Rebuilt and Painted










Camera Sites? Wairoa, Kawarau or Farm Bridge






3-7th September – Night Event






Rating Curve



QC4j







Thank you

